

1965-1967 MUSTANG CORE SUPPORT MODIFICATIONS


COPYRIGHT RON DAVIS RACING PRODUCTS, INC.

Applicable for part numbers 11-50MU66 and 11-16MU66T



PLEASE CALL IF YOU HAVE ANY
QUESTIONS 1-800-842-5166.

WWW.RONDAVISRADIATORS.COM



1. RE-POSITION BATTERY TRAY TO TRUNK.
(USE BATTERY RELOCATION KIT P/N 200900)

2. TRIM RAISED AREA THAT THE
ORIGINAL RADIATOR WAS
MOUNTED TO.

3. TRIM TOP OF CORE SUPPORT TO
CLEAR RADIATOR CAP AS NEEDED.
(SEE BELOW)



After trimming

